

Cafe SDK Release Notes

NINTENDO CONFIDENTIAL PROPRIETARY

2015 August

SDK Version 2.13.01

Introduction

This is a main-line release of the Cafe Software Development Kit.



To install the SDK, start by unzipping the base SDK package to a new location on your host PC, and then unzipping the Docs patch on top of it. Then refer to the MAN pages at `manual.html` in your installation, and then navigate to **Cafe SDK Basics** → **CAT-DEV QuickStart Guide** to continue setting up and using the SDK.

This SDK is intended for licensed game and application developers only.

Document Conventions

This document is organized by functional subsystem. Each subsystem is further subdivided into **New Features & Changes**, **Bug Fixes**, and **Known Issues**.

The following table shows the tags that are used to identify the importance of an issue.

Icon	Meaning
	A CAUTION .
	A BREAKING CHANGE . As the SDK continues to evolve, some changes may break existing applications. We regret the inconvenience.
[x]	An internal issue tracking identifier.

When referring to the MAN pages in these release notes, a **bold** title name means that you should open the named section by clicking on the arrow icon to expose its subsections. For more details, please see *HOW TO USE* in the MAN pages.

We hope this presentation improves the readability of this document, and we welcome your feedback.

Supported Platforms

This SDK officially supports the following Cafe Tool for Development (“CAT-DEV”) hardware systems:

- CAT-DEV MP (default)
- CAT-R MP

For more information about MP systems, please see the CAT-DEV release notes (`catdev_release_notes.pdf`).

For more information about CAT-R systems, please see the *CAT-R QuickStart Guide*.

Requirements and Dependencies

The following table lists SDK components and their dependencies.

Component	Requires	Version
SDK 2.13.01 Latest Update	Host Operating System	Windows 7 Service Pack 1 64-bit Edition
	Microsoft .NET Framework	.NET Framework 4.0 (Full)
	Visual C++ Redistributable Package	Visual C++ 2010 SP1 Redistributable Package (x64)
	Green Hills Software MULTI Tool Chain	5.3.24 or later as noted
	Boot Firmware	2.11.10M
CAT-DEV	Host Bridge Software	Min: 3.2.6.1; Recommended: 3.2.6.8
CAT-DEV	Host Bridge Firmware	Min: 0.0.14.74; Recommended: 0.0.14.80

Installing the MULTI Tool Chain

To install the Green Hills Software MULTI tool chain, please see **Cafe SDK Basics** → **CAT-DEV QuickStart Guide** → **Set Up Environment** → **Install the MULTI Tool Chain** in the MAN pages.

Installing the Host Bridge Software and Firmware

To install the Host Bridge Software, please see **Cafe SDK Basics** → **CAT-DEV QuickStart Guide** → **Set Up Environment** → **Set Up the CAT-DEV** in the MAN pages.

Updating the CAT-DEV

To update your CAT-DEV to this SDK, please use the `cafeupdate` command.

- For more details, please see **Cafe SDK Basics** → **Development Cycle** → **Update Environment** → **CAT-DEV System Update** in the MAN pages.

Subsystem Release Notes

Green Hills Software MULTI Release Notes

For the release notes for MULTI for Nintendo from Green Hills Software, please see these documents in the root of its installation package:

```
MULTI-<version>\MULTI for Nintendo Release Notes.pdf
```

```
MULTI-<version>\release_notes_ppc.pdf
```

where `<version>` is the GHS MULTI version, such as `5_3_22`.

For answers to frequently asked questions about MULTI for Nintendo, please see this document in the root of its installation package:

```
MULTI-<version>\MULTI for Nintendo FAQ.pdf
```

GX2 and GPU7 Graphics Core Release Notes

For the GX2 and the GPU7 graphics core release notes, please refer to the following MAN page in the SDK:

```
$CAFE_ROOT/system/docs/man/en_us/gx2/html2/gx2releasenotespage.html
```

nn Library Release Notes

For the Auto Connection, Nintendo Account, Friends Presence, SpotPass, Profanity Filtering, Software Keyboard, Error Viewer, NFP, and Temporary Directory release notes, please refer to the following MAN page in the SDK:

```
$CAFE_ROOT/system/docs/man/en_us/nn/public/API/html/release_notes.html
```

Table of Contents

1. Known Issues	4
2. System Performance	5
<i>Known Issues</i>	5
3. System Update	6
<i>Known Issues</i>	6
4. Dev Kit Tools and Functions	6
<i>Known Issues</i>	6
<i>SDK 2.13.01</i>	7
<i>SDK 2.13.00</i>	8
5. MULTI Compiler/Linker Tool Chain and Debugger	8
<i>Known Issues</i>	8
6. Cafe OS	9
<i>Known Issues</i>	9
<i>SDK 2.13.00</i>	10
7. Graphics and Video	10
<i>Known Issues</i>	10
8. Sound and Audio	11
<i>Known Issues</i>	11
9. Game Save	11
<i>SDK 2.13.00</i>	11
10. Game PADs (DRC, Wii Remotes, etc.)	11
<i>Known Issues</i>	11
<i>SDK 2.13.00</i>	12
11. Network	12
<i>Known Issues</i>	12
<i>SDK 2.13.00</i>	12
12. Mastering	13
<i>Known Issues</i>	13

1. Known Issues

This section summarizes the known issues in this SDK by subsystem. For more details, please follow the links to the detailed descriptions for each issue.

System Performance

Do not use the `dcbt` (data cache block touch) instruction.

Locked Cache DMA and Code Execution.

System performance may vary between SDKs.

Instruction Cache Intervention for the main application processor is disabled.

64B Prefetch Disabled When Locked Cache DMA is used on a particular core.

System Update

[10650] Do not update from SDK 2.06 or 2.07 to the latest SDK using a disc update.

[9559] After you install SDK 2.11.01, an attempt to run SDK 2.09.xx will fail.

Update of boot1 will fail when there are multiple directories under the update directory.


[4710] Do not update to a different SDK when in NAND mode.

Dev Kit Tools and Functions

[11735] Do not install the SDK in a directory with a long path name.

[11167] In PCFS boot mode, a `cafestop` command may be required between instances of `caferun` in some circumstances.

[11168] Rarely, the Windows host system may crash on a `cafex run` command.

 [10316,11150] An application's RPL files and any middleware it uses must all be built with the same version of the SDK as the application's RPX file.

[9621] With the latest Cygwin installed, pressing Ctrl-C when a title is running in a Cafe command window causes the command prompt to hang for about a minute.

Avoid using the standard C library function `realloc`.

The `caferun` command may choose any title instance to run when multiple titles with the same title ID are installed.

 [6970] Disc updating to SDK 2.09.02 fails the first time it is attempted in Development mode, always in Production mode.

[5512] How to estimate code area usage.

MULTI Compiler/Linker Tool Chain and Debugger

[9668] When a crash happens due to `OSPanic`, MULTI does not select the crashing `OSPanic` line upon launching.

Cafe OS

[11588] In very rare cases when loading an RPX or RPL, the system may panic.

[8951] Do not set thread affinity to `OS_THREAD_ATTR_AFFINITY_NONE` for any thread that may make a call to any `OSDynLoad*` function.

[10697] If an RPL erroneously has its own `main` function, then C++ constructors are called twice.


[5972] If a main application is in the background, a thread that runs continuously and does not wait on any blocking synchronization objects may cause a foreground switch to stall until this thread eventually blocks.

 [6447] Application code and data layout may differ between SDK versions.

 [4139] Issues with C++ exceptions.

 [4283] Do not access I/O request buffers after the corresponding I/O request has been started and before it has completed.

 [5460] Issues with Cafe OS runtime memory overhead.

 Threads affinized to more than one core that use floating point take a performance hit when rescheduled.

 Issues with `libc malloc` performance.

Graphics and Video

[8345] In the `drc/cameramic` demo, a buffer underflow error may appear after repeatedly closing and re-opening the camera.

[8837] Calling the `GX2SetPixelSamplerBorderColor`, `GX2SetVertexSamplerBorderColor`, `GX2SetGeometrySamplerBorderColor`, or `GX2SetComputeSamplerBorderColor` functions too frequently will result in a performance loss.

[3447] Noise may occur in the camera image if you change camera parameters while the camera is running.

[11417] Image corruption occurs at application shutdown if the application calls either of the `GX2Set{TV,DRC}Enable(GX2_FALSE)` functions from Core 0 before it releases foreground.

🔗 Many of the SDK demos depend on building the textures and shaders first.

Sound and Audio

[11020] When debugging a program using a debugger, it is possible for an AX voice to be dropped, especially when debugging audio callbacks.

[10611] In the MIX library, no sound is produced when both the initialized and new user-specified fader value are set to 0db.

[10951] Transition audio is played when starting a new process or when rebooting; during this time it is possible for a heartbeat failure to occur.

[8151] The Sound-1 library may produce different output for the PPC and DSP renderers.

Game PADs (DRC, Wii Remotes, etc.)

Audio noise may occur on the DRC in a bad wireless environment.

[10600] You are unable to update the firmware of a second GamePad when **Wii U GamePad (DRC) Setting** → **Multi DRC** is set to **ON** in System Config Tool.

🔗 The DRC Touch Screen may return a coordinate different from the touched location.

🔗 `VPADRead` may not return an error even if the DRC becomes disconnected during a system transition.

Network

[6048] Initial association fails for certain older routers when they are configured as WPA2 PSK AES.

WPS fails with certain older routers.

Mastering

🔗 Do not use the preloading feature with disc titles.

2. System Performance

Known Issues

Do not use the `dcbt` (data cache block touch) instruction.

- Espresso does not allow more than one outstanding data miss per core. If the prefetch generates a cache miss, a subsequent load/store that misses the cache will have to wait until the prefetch is done. With Espresso's 6-entry completion queue and the long latency to MEM2, the prefetching is unlikely to be effective. A normal load/store to demand fetch the data will often be a better choice.
- Likewise, avoid using the `DCTouchRange` function. With only one data miss outstanding, a loop of `dcbt` instructions will not allow data prefetching and computation to overlap.

Locked Cache DMA and Code Execution.

- While the LCDMA feature is presented through an asynchronous set of functions, the CPU core will busy wait until the DMA completes.
 - This is a workaround for a hardware issue present in all versions of the main application processor.
- Despite this workaround, a dramatic performance gain is still possible for LCDMA-based streaming code.

System performance may vary between SDKs.

- Performance optimization of the operating system and drivers continues. Some aspects of performance may worsen before they improve, because new features are matured and stabilized before they are tuned. These activities may span SDK releases.

Instruction Cache Intervention for the main application processor is disabled.

- This feature will not be available on the Cafe platform.

64B Prefetch Disabled When Locked Cache DMA is used on a particular core.

- This is a hardware bug that affects V4 and MP CAT-DEV platforms.
- This workaround will be removed for all hardware in a future SDK.

3. System Update

Known Issues

[10650] Do not update from SDK 2.06 or 2.07 to the latest SDK using a disc update.

- Instead, use the existing instructions for the appropriate platform in the MAN pages.

[9559] After you install SDK 2.11.01, an attempt to run SDK 2.09.xx will fail.

- As a workaround, run the “`cafex revert <target-sdk-root>`” command.
- For more details, please see the *CafeX: revert command* page in the MAN pages.

Update of boot1 will fail when there are multiple directories under the update directory.

- The default update directory is `$CAFE_ROOT\data\mlc\sys\update\pcfs`.
- The failure message is:

```
Update /vol/storage_hfiomlc01/sys/update/pcfs Failed: -262146
```

- To resolve this issue, please delete any directories under `$CAFE_ROOT\data\mlc\sys\update\pcfs` which are not originally packaged in the SDK.

[4710] Do not update to a different SDK when in NAND mode.

- You must be in PCFS mode to switch SDKs.
- For more details, please see **Cafe SDK Basics** → **Development Cycle** → **Run Applications** → **Environment Settings** → **Cafe Operating Modes** → **Boot Modes** in the MAN pages.

4. Dev Kit Tools and Functions

Known Issues

[11735] Do not install the SDK in a directory with a long path name.

- This can cause the SDK installation or builds to exceed the maximum Windows path length.


[11167] In PCFS boot mode, a `cafestop` command may be required between instances of `caferun` in some circumstances.

- In some circumstances, a second or subsequent `caferun` command may fail with the following log message:

```
PCFS: No response from PCFSServer, PCFS file system is unavailable!
```

- A workaround is to enter a `cafestop` command between `caferun` commands.

[11168] Rarely, the Windows host system may crash on a `cafex run` command.

 [10316,11150] An application's RPL files and any middleware it uses must all be built with the same version of the SDK as the application's RPX file.

- One known case is if the middleware is creating/managing GX2 display lists or GX2 contexts. This prevents potential memory corruption issues from occurring. But there are also other cases.

[9621] With the latest Cygwin installed, pressing Ctrl-C when a title is running in a Cafe command window causes the command prompt to hang for about a minute.

- This is a problem with recent releases of Cygwin.
- As a workaround, follow these steps:
 1. Open a second Cafe window. (Do not type Ctrl-C in the first window.)
 2. In the second Cafe window, type `cafestop`.

- The `cafestop` command will terminate the application and control will return back to the first Cafe window.

Avoid using the standard C library function `realloc`.


- Using the implementation of `realloc` in the Cafe SDK may significantly degrade performance.
- Developers should optimize their use of memory themselves so that calling `realloc` is rarely or never required.
- There is no plan to improve the implementation of `realloc` in the future.
- The source code for the Cafe SDK implementation can be found here:

```
$CAFE_ROOT/system/src/lib/def_malloc/cos_def_malloc.c
```

The `caferun` command may choose any title instance to run when multiple titles with the same title ID are installed.

- The search order depends on a number of factors that are not necessarily repeatable, including storage device attachment order.
- To run a specific instance of a title, please include the following option to `caferun`, selecting the desired device:

```
-e mcp:launch_hint:{hfiomlc,odd,mlc,hfiodisc}
```

 [6970] Disc updating to SDK 2.09.02 fails the first time it is attempted in Development mode, always in Production mode.

- If you burn an update disc with SDK 2.09.02 and try to perform an update from that disc, the system will crash just after Stage 0. In Development mode, if the system is powered down and restarted, the next update will succeed. In Production mode, the update will continue to fail.
- This failure is caused by the inclusion of the production updater and updater OS in SDK 2.09.02. On systems to be updated, the deprecated development updater and development updater OS are installed on the system. When the update is performed, the system does not know which updater to use and can pick the wrong one.
- The workaround for this failure is to run the update twice; or to avoid the crash, run Devmenu or System Config Tool and uninstall the old updater using the following steps:
 - In a `cafe.bat` window, run `cafeon`.
 - On the Game Pad, set the **System Mode to Development** if necessary:
 - **System Information** → **System Mode** → **Development** in Devmenu.
 - **Boot Configuration** → **System Mode** → **Development** in System Config Tool.
 - Use one of the following two methods; the second method avoids the crash:
 - Perform the update once, causing a crash, and then perform the update a second time.
 - Uninstall the development updater, and then perform the update. To uninstall the development updater:
 - On the Game Pad, navigate to **Title Manager** → **Launcher**.
 - Scroll down to the title with title ID **00050010100040FF**.
 - Press the **A** button to select this title.
 - Press the **Y** button to delete this title.
 - On SDK 2.08.01, Devmenu resets the settings to English and 49, respectively.
 - On SDK 2.07.03 and 2.08.02, Devmenu resets the settings to Japanese and 0, respectively.
 - This issue does not affect production games because the Wii U menu sets the language and country ID.
 - Developers may need to change the settings after system initialization, using the system config tool.

[5512] How to estimate code area usage.

- The only reliable way to estimate code area usage is to run the application, call `OSDynLoad_GetLoaderHeapStatistics`, and report the value of `mCodeHeap_MemBytesUsed`.
- Then pad that value by about 15% to account for temporary space used while processing relocations.
- For more details, please see the corresponding MAN page.

SDK 2.13.01

Bug Fixes

[CFENET-8776] Attempting to export certain save data from the System Config Tool without archiving it would cause the export to fail.

[11704] The MAN pages have been clarified in the usage and location of the `CAFE_CODE_DIR` and `CAFE_META_DIR` directories.

- For more details, please see **Create an Application → Preparing Your Application → Application Configuration → meta.xml** in the MAN pages.

[11809] The MAN pages have been updated to reflect that environment variables are limited to 255 characters, including the terminating NUL character.

- For more details, please see **Devkit API → Environment → ENVGetEnvironmentVariable** in the MAN pages.

[11790] The MAN pages have been updated to show how to specify an ELF file for debugging when running a `wumad` file with the `cafex discrun` command.

- For more details, please see the corresponding MAN page.

[11740][11762][11771][11773][11774][11775][11787][11793][11794][11797][11811] Many minor editorial changes have been made to improve the quality and consistency of the MAN pages.

- Included in this fix is better agreement between MAN page and header file definitions.

SDK 2.13.00

New Features and Changes

[CFENET-3704] The **Save Data Manager** in the System Config Tool now has a **Delete All Fill-up Save Data** command that batch-deletes dummy save data created with the fill-up tool.

Bug Fixes

[11520] `preprpl` could fail with a segmentation fault when a very large `.def` file contained Unix-style line endings.

[CFENET-8182] The system would halt when attempting to start an overlay application via the product version of the HOME Button Menu from the System Config Tool.

[CFENET-8511] In the System Config Tool, an NTSC/PAL setting change made in the **Display and Audio** menu would revert to its previous setting after changing the game region or platform region.

[CFENET-8585] In the System Config Tool, if something other than the 4-digit number was entered in the Parental Controls menu, the setting would not change, but the display would indicate that it had changed.

[CFENET-8590] In the System Config Tool Title Launcher screen, the device information and subsequent information for the title were shown in the wrong position.

[CFENET-8593] When running the System Config Tool on a `DEBUG` OS, the system would hang if you attempted to exit with the network settings unconfigured.

[CFENET-6428] System Config Tool now has an **Account Manager** menu item for directly starting the account manager.

[CFENET-8251] The System Config Tool now loads an account if started without an account loaded.

- If a default account exists, the default account is loaded; otherwise, the account in slot 1 is loaded.

[8990] There is a new command to install a title to emulated MLC: `cafex install`.

- For more details, please see **Cafe SDK Basics → Development Cycle → Run Applications → Tools to Run Applications → cafex → cafex install**.

[11519] The `-e mcp:launch_hint:` option now accepts `sddisc` as a target.

- For more details, please see **Cafe SDK Basics → Development Cycle → Run Applications → Tools to Run Applications → caferun**.

[10851] Multibyte output from `cafex` was corrupted every 128 bytes.

[10973] Reliability of kill-restart scenarios has been improved.

- An example case is relaunching an application in `MULTI`.
- If a soft launch fails, Cafe will now cold boot to the title.

[11385] The `CAFE_META_DIR` environment variable now appears in the initial Cafe command banner.

5. MULTI Compiler/Linker Tool Chain and Debugger

Known Issues

[9668] When a crash happens due to `OSPanic`, `MULTI` does not select the crashing `OSPanic` line upon launching.

- You can locate the offending line, or its caller, by examining the call stack. This can be done by clicking the “call stack” button in MULTI.
 - If the `OSPanic` occurs with “`make run`”: The call stack shows the caller to the function where `OSPanic` happens. The caller function should be a level immediately above a system function.
 - If the `OSPanic` occurs with “`make multirun`”: The call stack shows the system function `__OSPanic()` as the crash point. The user function that caused the crash should be immediately above the system function `OSPanic()`.

6. Cafe OS

Known Issues

[11588] In very rare cases when loading an RPX or RPL, the system may panic.

- The loader returns most errors to the kernel or the application if an error occurs while loading an RPX or RPL.
- When the application does not get the error, in most cases the system shows the appropriate error display, but there are some very rare cases in which the system panics.

[8951] Do not set thread affinity to `OS_THREAD_ATTR_AFFINITY_NONE` for any thread that may make a call to any `OSDynLoad*` function.

- Loading an RPL can fail if the calling thread has affinity `OS_THREAD_ATTR_AFFINITY_NONE`.

[10697] If an RPL erroneously has its own `main` function, then C++ constructors are called twice.

- If an application uses C++, and it also uses an RPL that has its own `main` function in addition to the RPX’s `main` function, then C++ constructors are called twice.
- An RPL should not have its own `main` function but the `makerpl` tool does not check for this.
- There are two possible workarounds:
 1. Change the name of the RPL’s `main` function to something else.
 2. Use the MULTI compiler option `--disable_ctors_dtors` when building the RPL. This option tells the compiler to omit the call to `_main` at the beginning of the RPL’s `main` function. The static initializers are still created, but they will only be called once from the RPX’s `main` function.
- This will be resolved in a future SDK release.

[5972] If a main application is in the background, a thread that runs continuously and does not wait on any blocking synchronization objects may cause a foreground switch to stall until this thread eventually blocks.

- This is most commonly seen when returning from the Home Button Menu to the main application.

 [6447] Application code and data layout may differ between SDK versions.

- For example, developers should not make any of the following assumptions when comparing a session run on one release of the SDK with a session run on a different release of the SDK:
 - that raw pointer addresses stored during the first session will be valid during the second session;
 - that corresponding allocations from the heap will be at the same addresses;
 - or that the RPX and the RPLs that it uses will be loaded at the same addresses.
- Please audit your software to ensure that there are no assumptions about code or data start addresses.
- If you find that your software does make such assumptions, please contact Nintendo Developer Support immediately.

 [4139] Issues with C++ exceptions.


- In order to use C++ exceptions, the RPX containing the main program must have exceptions enabled.
 - Thus, if a dynamic library uses C++ exceptions, then the RPX that links to it (directly or through another RPL) must enable exceptions.
- Do not throw exceptions in routines that may be called by Cafe OS.
 - Thus, Cafe OS callbacks cannot throw exceptions.
 - Instead, signal an exception in some other manner (for example, set a flag, send a message) to other code that can handle the exception.
- The `try` keyword incurs significant runtime overhead.

 [4283] Do not access I/O request buffers after the corresponding I/O request has been started and before it has completed.


- It is extremely important that no access of the I/O request buffer(s) occur after the request has been started.
- Otherwise, data returned from the request buffer(s) may appear to be corrupted.
- Attempting to “race” or time the arrival of data within the I/O buffer and modify it after it arrives is illegal with Cafe OS. Once an I/O operation starts, Cafe OS is the owner of the destination buffer until the I/O operation completes.
- Cafe OS does not currently have a mechanism to police or enforce this prohibition, so developers must be on their best behavior to prevent access to the request buffer(s).

 [5460] Issues with Cafe OS runtime memory overhead.

- During process execution, Cafe OS imposes additional runtime overhead upon each process. For instance, the user-mode operating system components place per-process data within the address-space of each process. The amount of overhead can be discovered by using the `OSGetMemBound` API as demonstrated in the `replace_core_user` demo.
- Developers should plan for this small overhead.
- It may be necessary to change the `MAX_CODESIZE` value in `app.xml` to account for the increased code size.
- For more details, please see **Operating System** → **Cafe Core OS (COS) Overview** and the `OSGetMemBound` API MAN pages.

 Threads affinitized to more than one core that use floating point take a performance hit when rescheduled.

- The overhead comes from synchronizing the FPU state between the processor cores.
- There is no overhead if all threads are affinitized to a single core.

 Issues with `libc malloc` performance.

- `malloc` performance may suffer if you allocate many blocks, due to fragmentation. To alleviate this, we recommend pre-allocating a large, contiguous heap for `malloc` by issuing this call:

```
free(malloc(initial_size)); // where initial_size is the desired malloc heap size
```

SDK 2.13.00

Bug Fixes

[11200] If an RPL or RPX was an exact multiple of 4MB in size, the file could fail to load with error 160-2224.

7. Graphics and Video

Known Issues

[8837] Calling the `GX2SetPixelSamplerBorderColor`, `GX2SetVertexSamplerBorderColor`, `GX2SetGeometrySamplerBorderColor`, or `GX2SetComputeSamplerBorderColor` functions too frequently will result in a performance loss.


- Beginning with SDK 2.11.01, these functions have an added GPU flush and wait idle to prevent graphics corruption.
- As a result, calling these functions too frequently will result in a performance loss.
- Application developers are advised to only call these functions when necessary.

[3447] Noise may occur in the camera image if you change camera parameters while the camera is running.

- The most noticeable example is changing gamma values. If you change the gamma, noise will occur in horizontal lines.
- Noise may not be as noticeable when changing other parameters. However, if you make a significant change, you may notice noise.
- As a workaround if noisy images are noticeable, you may skip two frames following parameter changes, change parameters only when opening the camera, or make small parameter changes.

[11417] Image corruption occurs at application shutdown if the application calls either of the `GX2Set{TV,DRC}Enable(GX2_FALSE)` functions from Core 0 before it releases foreground.

- As a workaround, do not call `GX2Set{TV,DRC}Enable(GX2_FALSE)` before releasing the foreground.

 Many of the SDK demos depend on building the textures and shaders first.

- This requirement was added to help reduce the size of the SDK package.
- To build the textures and shaders, please run the following command in a Cafe SDK shell:

```
make -C $CAFE_ROOT/system/src/demo
```

8. Sound and Audio

Known Issues

[11020] When debugging a program using a debugger, it is possible for an AX voice to be dropped, especially when debugging audio callbacks.

[10611] In the MIX library, no sound is produced when both the initialized and new user-specified fader value are set to 0db.

- A previous fix has been reverted due to other issues with it. This revert restores the prior behavior.

[10951] Transition audio is played when starting a new process or when rebooting; during this time it is possible for a heartbeat failure to occur.

- The occurrence rate is very low, but the logs will show a message similar to:

```
--- User Heartbeat Timeout Core0 limit:10---
```

[8151] The Sound-1 library may produce different output for the PPC and DSP renderers.

- In the Sound-1 library, the PPC renderer can overdrive saturation when a 0dB signal is configured to be boosted by +6dB, resulting in a difference in the outputs between the PPC and DSP renderers.
- This issue is fixed in the new Sound-2 library, but remains in Sound-1.

9. Game Save

SDK 2.13.00

Bug Fixes

[CFENET-8209] When updating the save data for a demo title, the timestamp of the demo title itself was updated instead of the timestamp for the demo title's save data.

[CFENET-8521] If a disc is removed while the `SAVEInitSaveDir` function is being called, it is now treated as a fatal error to indicate that the disc was removed.

- Previously, the `SAVE_STATUS_NOT_FOUND` error was erroneously returned to the application in this case.

10. Game PADs (DRC, Wii Remotes, etc.)

Known Issues

DRC

[8345] In the `drc/cameramic` demo, a buffer underflow error may appear after repeatedly closing and re-opening the camera.

- The DRC mic driver is correct; the demo's handling of camera restart and foreground/background switching is the issue.

Audio noise may occur on the DRC in a bad wireless environment.

- Depending on the wireless environment, the DRC audio stream could be interrupted for a few milliseconds.
- This noise results from the DRC system design and is unavoidable.
- If there are no such interruptions when you play the same audio source on the TV, this is most likely the issue.

[10600] You are unable to update the firmware of a second GamePad when **Wii U GamePad (DRC) Setting** → **Multi DRC** is set to **ON** in System Config Tool.

- As a workaround, you may temporarily install the second GamePad as the first GamePad, update its firmware, and then re-install it as the second GamePad.

🔗 The DRC Touch Screen may return a coordinate different from the touched location.

- Rarely, the DRC Touch Screen may return a coordinate different from the location that was actually touched.
- This issue's frequency varies by how you touch the screen:
 - When making firm contact using the special stylus, it happens once every several thousand times.
 - It happens more often when touching lightly or when touching with a finger.

- Normally, if the value from Touch Screen is uncertain (cannot be guaranteed), the `validity` field of `VPADTPData` will be one of the `VPAD_TP_VALIDITY_INVALID_*` values. However, in this case, even though `validity = VPAD_TP_VALIDITY_VALID`, an uncertain value is still returned.
- When input errors are not acceptable, such as when offering an important choice, use two or more frames-worth of coordinate data instead of one to determine the input.

 `VPADRead` may not return an error even if the DRC becomes disconnected during a system transition.

- If the DRC becomes disconnected during a system transition, due to a lost battery or wireless connection, a disconnection event may not be sent even though DRC is not connected.
- For example, if the DRC disconnects while moving from the HOME button menu to the application, `VPADRead` may not return `VPAD_READ_ERR_NO_CONTROLLER` and keep returning `VPAD_READ_ERR_NO_DATA`.
- If this error continues for 10 seconds or longer, you can assume that the DRC has been disconnected.
- If the DRC becomes reconnected during this condition normal behavior will resume.

SDK 2.13.00

Bug Fixes

[11420] The MAN page for `HIDWrite` has been updated with descriptions for possible error codes.

[11761,11764] The MAN pages related to `usb_mic_ringbuffer_t`, `usb_mic_state_t`, and `usb_mic_status_t` have been updated with descriptions for all of their elements.

11. Network

Known Issues

[6048] Initial association fails for certain older routers when they are configured as WPA2 PSK AES.

- D-Link DI-524 vC1, DI-624 vC3.

WPS fails with certain older routers.

- [4835] ZyXEL NBG318S, NBG334W, X550N.
- [6047] Linksys WRT350N

SDK 2.13.00

Bug Fixes

[10621] The `SOShutdown` function no longer discards pending send data in the socket buffer when `SHUT_WR` is specified.

[11351] The MAN page for `curl_easy_setopt` has been updated to clarify that `CURLOPT_NOSIGNAL` is not supported.

- For more details, please see the corresponding MAN page.

[11368] The `SOConnect` function could unexpectedly return `SO_EADDRINUSE`.

- This would happen when there was an open socket bound to a local port in the same range as that local ports are automatically bound, and if another socket was trying to be automatically bound to that same local port (usually after the maximum auto-port is used and it wraps around to the beginning).

[11567] New function `NSSLContextSetMode` has been added.

- For more details, please see **Network** → **SSL** → **API Overview**, **Network** → **SSL** → **Demo**, and the corresponding function in the MAN pages.


[11722] The `SOGetHostByName` function could fail due to incomplete expansion of a label-compression form in a DNS message.

[11772] The MAN page for the `NSSLExportInternalServerCertificate` function has been updated to clarify that the buffer size for the `pCertBufSize` parameter must be aligned to `NSSL_IO_BUFFER_ALIGN`.

[11805] The MAN page for the `NSSLExportInternalServerCertificate` function has been updated to clarify that a returned cert size is not necessarily a multiple of `NSSL_IO_BUFFER_ALIGN`.

12. Mastering

Known Issues

 Do not use the preloading feature with disc titles.

- If the preloaded title disc contains the CafeSDK 2.08-series update partition, you will encounter the following problem:
 - Once a disc is inserted, it should normally take about 10 to 20 seconds to display the icon on the Wii U menu. However, it will take 40 seconds instead, and you will hear the disc drive seeking.
- For more details, please see **Cafe SDK Basics** → **Development Cycle** → **Master Applications** → *Preloading Applications* in the MAN pages.